

The Party Corner

19 E. Newman Springs Rd. Shrewsbury, N.J. 07702

732-741-0040 Fax: 732-747-1589

www.partycorner.com

Email: partycorner@msn.com

"So many reasons to party...but only one place to shop!"

Since 1969, serving all your party and event rental needs.

OPERATING INSTRUCTIONS

POPCORN

OPERATING INSTRUCTIONS

CONTROLS AND THEIR FUNCTIONS

LIGHT AND WARMER SWITCH

Turns on the heat to the bottom corn pan and heat light.

KETTLE MOTOR SWITCH

Turns on the motor which drives kettle agitator shaft.

KETTLE HEAT SWITCH Turns on the heat element

POPPING INSTRUCTIONS

1. Turn KETTLE HEAT and KETTLE MOTOR switch ON.
2. Make test pop with 3 kernels of corn and 1 oz. (30 ml) of oil.
3. Load pre-measured popcorn and oil pouch into kettle.
4. When corn has popped, dump kettle.
5. Repeat cycle starting with Item #3; always pop 3-5 batches for best popcorn.

Each time you finish a series of poppings, allow the kettle to cool, then wipe the outside of the kettle with a soft cloth to remove any oil drippage on the outside of the kettle. After you finish popping for the day, allow kettle to cool until it is not too hot to touch, but still warm. Unplug kettle and remove it from the machine. With a cloth, wipe out the inside of the kettle, kettle lid, crossbar, outside and underneath of the kettle. Note: Never put the kettle in a sink to clean.

CLEAN THE KETTLE (DAILY)

1. After popping corn, and allowing the kettle to cool, wipe the kettle with a clean cloth. It is easy to keep the outside clean when the kettle is warm and the oil is not baked on.

CAUTION: The hot kettle will cause burns if you touch it with your hand. Allow the kettle to cool for at least 1 hour before attempting to clean.

2. Every night, add 10 – 12 oz. of Heat'n Kleen solution (mix 2 tablespoons Heat'n Kleen per gallon of water). Turn on the kettle heat. When the water starts to boil, turn off the heat and let it work overnight.

3. The next morning, dump the solution into a bucket and wipe the inside of the kettle with a cloth. Cleaning the cabinet of your machine is easy. Take a clean cloth and wipe excess grease from the glass. Wipe the outside of the machine also.

NOTE: Never use a glass or plastic cleaner that contains ammonia. It will crack